



# Frame Verification Chart



## Legend

—○— = 180 Line Symbol  
**N<sub>s</sub>** = Single vision  
**N<sub>p16</sub>** = Progressive 16  
**N<sub>p18</sub>** = Progressive 18  
**N<sub>om</sub>** = Office Meeting  
**N<sub>oc</sub>** = Office Computer

**50** = 1.50 Plastic (above nasal 180 Line Symbol)  
**53** = 1.53 Trivex (above nasal 180 Line Symbol)  
**59** = 1.59 Polycarbonate (above nasal 180 line symbol)  
**60** = 1.60 High Index (above nasal 180 line symbol)  
**67** = 1.67 High Index (above nasal 180 line symbol)  
**74** = 1.74 High Index (above nasal 180 line symbol)  
**200** = Add Power (Range 050-400)

To print this measuring chart at the correct size from Acrobat Reader:

1. Go to File, then select **Print**
2. Under Page Sizing & Handling options, select **Actual Size**
3. Click on **Print** button to print

**Note:** Chart measurements will be incorrect if you select "fit" or other page-scaling options.

It is recommended to verify the printed chart is the correct size with a ruler.